

EAST Search History

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	6	(penetrometer\$3 or (penetrat\$4 near3 (measurement or measur\$3 or meter \$3))) near7 (soil or earth) and (axial near3 (force or stress or strain or load or pressure or compress\$3) near3 (sens\$3 or detect\$3 or transducer or indicat\$3 or gage or gauge))	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/04/10 10:56
L2	75	(penetrometer\$3 or (penetrat\$4 near3 (measurement or measur\$3 or meter \$3))) near7 (soil or earth) with (shaft or spinndle or rod)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/04/10 11:13
L3	3	(penetrometer\$3 or (penetrat\$4 near3 (measurement or measur\$3 or meter \$3))) near7 (soil or earth) with (sphere or spherical\$3)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/04/10 11:30
L4	10	(penetrometer\$3 or (penetrat\$4 near3 (measurement or measur\$3 or meter \$3))) near7 (soil or earth) same (sphere or spherical \$3)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/04/10 11:31
L5	36	(penetrometer\$3 or (penetrat\$4 near3 (measurement or measur\$3 or meter \$3))) near7 (soil or earth) and (sphere or spherical\$3)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/04/10 11:32

4/10/08 11:36:54 AM

C:\Documents and Settings\TBellamy\My Documents\EAST\workspaces\10593546.wsp